
Percent Obstructed by Damage

- 0.2
- 0.3
- 0.4
- 0.5
- 0.7
- 0.95



0 625 1,250 2,500 3,750 5,000 Feet

Figure 5-3
Study Area Damaged Culverts

Big Lake Drainage Management Plan

MONTGOMERY WATER GROUP, INC.
Water Resources Engineering